Set de verificación de calibración para HI 755
HI755-11

Descripción

El set de verificación de calibración de alcalinidad marina Checker® HC **HI755-11** proporciona una solución simple para validar la alcalinidad marina Checker® HC **HI755** que tiene un rango de 0 a 300 ppm $CaCO_3$. Este conjunto de estándares de alta calidad se fabrica en nuestras instalaciones de última generación y se suministra con un certificado de análisis. El certificado de análisis proporciona el número de lote, los valores de referencia y la fecha de vencimiento para la trazabilidad al certificar el Checker®HC.

Especificaciones

No Especifica

Accesorios

No Especifica

Cómo pedir

No Especifica

Ventajas

El **HI755-11** es un conjunto de estándares de calibración de alta calidad que permite a los usuarios validar la alcalinidad marina Checker® HC **HI755**. El **HI755-11** incluye una cubeta sellada para cero ppm de $CaCO_3$ y una cubeta teñida para una muestra equivalente a 100 +/- 10 ppm de $CaCO_3$ a 25 °C.

-Suministrado con certificado de análisis:

- Código de producto
- Número de lote
- Fecha de caducidad

HANNA instruments

CERTIFICATE OF ANALYSIS

Product Name: CALIBRATION CHECKING SET FOR HI 711
Product Code: [illegible]
Lot number: SC0372/14
Expiration date: [illegible]ber 2017

Standard cuvette	Lot number	Standard Value @ 25°C (ppm)	Passed
A, HI 711-11	[illegible]038	[illegible]	✓
B, HI 711-11	2039	[illegible] ± 0.05	✓

Hanna Instruments certifies these standards meet the stated tolerance limits as indicated. These should be used for [illegible]y contr[illegible] to validate instrument function on the specified Hanna in[illegible] only. [illegible]re standards in the storage box upright at room tempera[illegible]e. Do [illegible] standard cuvettes.

Instructions for use:

1. Thoroughly wipe standard cuvette with HI731318 [illegible]ree cloth and only handle using top of cuvette. The cuvette wall must be dry and free of smudges.
2. At the C.1 prompt place A, HI 711-11 standard [illegible]vette into the h[illegible] of the Checker and press operations button.
3. At the C.2 prompt place B, HI 711-11 standard cuvette i[illegible] holder an[illegible] press the operations button.

Acceptable results must be between 0.95 and 1.05 ppm @ [illegible]°C.

File number: CERT711-11 _SC0372/14
QA manager: Bogdan Munteanu

SAMPLE

Video

No Especifica