Set de Verificación de Calibración de Amoníaco para Checker® HC
HI700-11

Descripción

El Set de Verificación de Calibración de Amoníaco para Checker® HC - **HI700-11** proporciona una solución simple para validar el Checker® HC para Amoníaco de Rango Bajo - **HI700**. Este set de estándares de alta calidad se fabrica en nuestras instalaciones de última tecnología y viene con un Certificado de Análisis. El Certificado de análisis proporciona el número de lote, los valores de referencia y la fecha de vencimiento para la trazabilidad al verificar el Checker® HC.

Especificaciones

Product Name	Set de Verificación de Calibración de Amoníaco para Checker® HC - **HI700-11**

Quote Required	No
Certificado de Análisis	Sí
Envase	Cubetas
Cantidad de Análisis	1 juego

Accesorios

No Especifica

Cómo pedir

No Especifica

Ventajas

El **HI700-11** incluye una cubeta sellada para cero ppm de amoníaco y una cubeta con coloración equivalente a 1.50 +/- 0.10 ppm a 25˚C de amoníaco.

-Reutilizable con larga vida útil

-Suministrado con Certificado de Análisis, el cual incluye :

- Código de producto
- Número de lote
- Fecha de caducidad



HANNA instruments

CERTIFICATE OF ANALYSIS

Product Name: CALIBRATION CHECKING SET FOR HI 711
Product Code: [illegible]
Lot number: SC0372/14
Expiration date: [illegible]ber 2017

Standard cuvette	Lot number	Standard Value @ 25°C (ppm)	Passed
A, HI 711-11	[illegible]038	[illegible]	✓
B, HI 711-11	2039	[illegible] ± 0.05	✓

Hanna Instruments certifies these standards [illegible] stated tolerance limits as indicated. These should be used for [illegible]y contr[illegible] to validate instrument function on the specified Hanna in[illegible] only. [illegible]re standards in the storage box upright at room tempera[illegible]e. Do [illegible]tandard cuvettes.
Instructions for use:
1. Thoroughly wipe standard cuvette with HI731318 [illegible]ree cloth and only handle using top of cuvette. The cuvette wall must be dry and free of smudges.
2. At the C.1 prompt place A, HI 711-11 standard [illegible]vette into the h[illegible] of the Checker and press operations button.
3. At the C.2 prompt place B, HI 711-11 standard cuvette i[illegible]older an[illegible] press the operations button.
Acceptable results must be between 0.95 and 1.05 ppm @ [illegible]°C.

File number: CERT711-11 _SC0372/14
QA manager: Bogdan Munteanu

SAMPLE

Video

No Especifica